




# M 5.8, 104 km S of Champerico, Guatemala

Origin Time: 2020-08-04 19:17:52 UTC (Tue 13:17:52 local) Location: 13.3527° N 91.9520° W Depth: 11.8 km

## **PAGER** Version 4

Created: 1 day, 0 hours after earthquake



**Estimated Population Exposed to Earthquake Shaking** 

ESTIMATED POPULATION EXPOSURE (k=x1000)		_*	76k*	172k	0	0	0	0	0	0
ESTIMATED MODIFIED MERCALLI INTENSITY		I	11-111	IV	V	VI	VII	VIII	IX	X+
PERCEIVE	SHAKING	Not felt	Weak	Light	Moderate	Strong	Very Strong	Severe	Violent	Extreme
POTENTIAL DAMAGE	Resistant Structures	None	None	None	V. Light	Light	Moderate	Mod./Heavy	Heavy	V. Heavy
	Vulnerable Structures	None	None	None	Light	Moderate	Mod./Heavy	Heavy	V. Heavy	V. Heavy


<sup>\*</sup>Estimated exposure only includes population within the map area.

# Population Exposure

population per 1 sq. km from Landscan



Overall, the population in this region resides in structures that are a mix of vulnerable and earthquake resistant construction. The predominant vulnerable building types are mud wall and adobe block with concrete bond beam construction.



#### **Historical Earthquakes**

Date	Dist.	Mag.	Max	Shaking
(UTC)	(km)		MMI(#)	Deaths
2001-02-17	311	4.1	V(2,250k)	1
2001-05-08	338	5.7	VII(562k)	1
1976-02-04	371	7.5	IX(80k)	23k

Recent earthquakes in this area have caused secondary hazards such as landslides that might have contributed to losses.

### **Selected City Exposure**

nom acorvanies.org					
MMI	City	Population			
IV	Nueva Concepcion	11k			
Ш	La Gomera	24k			

bold cities appear on map.

(k = x1000)

PAGER content is automatically generated, and only considers losses due to structural damage. Limitations of input data, shaking estimates, and loss models may add uncertainty.